

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

(1) County Putnam  
 (2) Township \_\_\_\_\_



(3) DEC Well Number P1618


**WELL COMPLETION REPORT**

(4) OWNER Schoonmaker Homes  
 (5) ADDRESS 275 Route 17K Newburgh NY 12550  
 (6) LOCATION OF WELL (See Instructions On Reverse) Lane Gate Rd., Cold Spring  
 Show Lat/Long if available and method used:  
 GPS  DEC Website  Map Interpolation N 41° 25.962 W 73° 55.192

LOG \*  
 Ground Surface EL. \_\_\_\_\_ ft. above sea level  
 Top Of Casing is located 2+ ft. above (+) or below (-) ground surface


(7) DEPTH OF WELL BELOW LAND SURFACE (Feet) 230'  
 (8) DEPTH TO GROUNDWATER BELOW LAND SURFACE (Feet) 15 DATE MEASURED 1-25-01

**CASINGS**  
 (9) DIAMETER 6 in. | | | | in.  
 (10) LENGTH 20 ft. | | | | ft. | | | | in.  
 (11) GROUT TYPE / SEALING  
 (12) GROUT / SEALING INTERVAL (Feet) FROM \_\_\_\_\_ TO \_\_\_\_\_




**SCREENS**  
 (13) MAKE & MATERIAL  
 (14) OPENINGS  
 (15) DIAMETER in. | | | | in.  
 (16) LENGTH ft. | | | | ft. | | | | in.  
 (17) DEPTH TO TOP OF SCREEN, FROM TOP OF CASING (Feet)

**YIELD TEST**  
 (18) DATE 1-25-01  
 (19) DURATION OF TEST 1 hour  
 (20) LIFT METHOD  Pump  Air Lift  Bail  
 (21) STABILIZED DISCHARGE (GPM) 15  
 (22) STATIC LEVEL PRIOR TO TEST (feet/inches below top of casing)  
 (23) MAXIMUM DRAWDOWN (Stabilized) (feet/inches below top of casing)  
 (24) RECOVERY (Time in hours/minutes)  
 (25) Was the water produced during test discharged away from immediate area? Yes \_\_\_ No \_\_\_



**PUMP INSTALLATION**  
 (26) PUMP INSTALLED? YES \_\_\_ NO \_\_\_  
 (27) DATE  
 (28) PUMP INSTALLER  
 (29) TYPE  
 (30) MAKE  
 (31) MODEL  
 (32) MAXIMUM CAPACITY (GPM)  
 (33) PUMP INSTALLATION LEVEL FROM TOP OF CASING (Feet)

(34) METHOD OF DRILLING  Rotary  Cable Tool  Other Percussion  
 (35) USE OF WATER (see instructions for choices) Domestic  
 (36) DATE DRILLING WORK STARTED 1-25-01  
 (37) DATE DRILLING WORK COMPLETED 1-25-01  
 (38) DATE REPORT FILED 2-16-01  
 (39) DRILLER & COMPANY Anthony P. A. Halla Southeast Well Drilling  
 (40) DEC REGISTRATION NO. 10151



\* Show log of geologic materials encountered with depth below ground surface, water bearing beds and water levels in each; casings; screens; pump; additional pumping tests and other matters of interest, e.g., water quality (sulphur, salt, methane). Describe repair work. Attach separate sheet if necessary.

BOTTOM OF HOLE