9-187
July 1918

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES BRANCH

Carmel 15' quad
(5) 9:05, 35E
call number
[illegible]

Deep?
Croton Falls 7½' quad.

Spring Schedule

Date 7-14-50, 1950 Field No. SP103

Record by G. Grossman Office No.

1. *Location:* State NYS Tn. of Carmel County Putnam
Quadrangle Croton Falls 7½' quad.
2 mi NW of Croton Falls ¼ sec. T N S R. E W
2. *Owner* N. Ellenbogen Address Stebbins Road
Name [illegible] of Carmel Croton Falls, N.Y.
3. *Topography* hillside
4. *Altitude* 350 ft. above ✓ below sea
5. *Kind of rock* till
6. *Structure* no big boulders
small cobbles in soil
7. *Openings:* Number Character
Source till, 8
8. *Improvements, accommodations* Cemented fieldstone collecting basin - 2' dia (round) x 4 ft. deep. & cem. field. house & roof
9. *Yield* Gal. Min. Meas., Rept.
Fluctuation
Dependability ran dry for first time in summer of 1949
10. *Use:* Dom., Stock, Irr., Med., Bath, Bottling
Quantity overflowing about 1-1½ GPM now
11. *Quality:* Good, fair, bad Sample Yes No
Taste, odor, color
Temp. (°F.) 51.5° - measured, 7-14-50
Gases: Quantity Character
Unfit for
Sanitation
12. *Deposits:* Kinds none Quantity
Features
Sketch map, analysis ✓ call on back page

U. S. GOVERNMENT PRINTING OFFICE 6—8070