9-187
July 1918

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
WATER RESOURCES BRANCH

Carmel 15' Quad
15 Y. 0.6 N. 5.4 E

SP93

see SP92

Spring Schedule

Date 5-27-50, 1956 Field No.

Record by DeGrossman from Gordon Perkins Office No. see SP92 & P484

1. *Location:* State N.Y. Caretaka County Putnam

Quadrangle Clove 15' quad

Town of Patterson ¼ sec. T N S R. Mooney Hill E W

2. *Owner* William Palmer Dixon Address RFD Patterson, N.Y.

Name

3. *Topography* slope, small valley

4. *Altitude* 905 ft. above ✓ below sea

5. *Kind of rock* till

6. *Structure*

bedrock outcrops nearby.

7. *Openings:* Number Character

Source

8. *Improvements, accommodations* Wooden protecting shed 3/8" lead pipe to barn.

9. *Yield* small flow. Gal. Min. Meas., Rept.

Fluctuation Has never run dry.

Dependability

10. *Use:* Dom., Stock, Irr., Med., Bath, Bottling

Quantity

11. *Quality:* Good, fair, bad Sample Yes ✓ No

Taste, odor, color

Temp. (°F.)

Gases: Quantity Character

Unfit for

Sanitation

12. *Deposits:* Kinds Quantity

Features

Sketch map, analysis for sketch see SP92 on back page

U. S. GOVERNMENT PRINTING OFFICE 6—8070