

Brookly - Hammond Station Ct.
 Newark
 ...

LOG OF WELL

KIND OF ROCK OR OTHER MATERIAL (Give color and tell whether hard or soft)	DEPTH, IN FEET		THICKNESS, IN FEET	REMARKS (Especially information as to water found)
	From—	To—		
Soil made land	0	8	8	
Soil	8	9 1/2	1 1/2	
Light colored sand & gravel (gray clay)	9 1/2	19	9 1/2	
Light colored sand & gravel	19	62	43	Lots of water
White limestone (soft)	62	327	265	
<p>Test pump at 3 pm at 160' ft for 8 hrs & stayed there</p> <p>Discharge (from casing) from Drillers pump Sundry Engineers</p> <p>John E. Riordan Valley Rd. New Canaan Conn</p>				
Turbidity P.P.M.	11-8-52	11-14-52	70' 6" - soft	
Color "	15.	note	75' - harder	
Alkalinity Ca Co ₃ (Total)	3.	note	80' - hard	
Carbonates (alkalinity)	40.	still can't tap	83' - 6" - soft for 6"	
Bicarbonates (alkalinity)	3.	carbon	84' - 90' hard	
Total hardness	37.	alkalinity	90 - 91 soft	
Chlorides	300.	not determined	91' - hard to 93'	
Iron total	50.	X	93 soft	
Calcium as Ca	0.15	3.0	94' 6" hard	
Magnesium as Mg.	48.		at 95' soft	
Sulfates - cause of most hardness	42.		100' 6" - hard for a few "	
note: water described as high in SO ₄ & Ca. well	260.		105' - soft in between	
			hard again for a few "	
			1113' - " " " "	
			114' 6" - hard	
			118' - hard	

Check to see why this shows a high SO₄ and a low bicarbonate - Art Beaten!

No. from ~~Brady~~
records.

Brady-Stamond Motor Co.
Brewster

Date: January 1949

Casing: 77' 4"

Depth of well: 160'

Yield: 3 gpm

S.W.L. = 29 ft.

Is this in another
part of Brewster?



BRADY-STANNARD MOTOR CO., INC. Jct. of rout
6 & 22, Brewster, N. Y. CHEVROLET, OLDSMOBILE,
CADILLAC sales and service.
Modern and complete facilities for handling every type
auto repair by factory trained mechanics. Our large
volume enables us to give you top dollar value. We
invite your patronage.

PLACE
STAMP
HERE

Cont from below

150 - seam
160' - hard
160-177 soft
177 - hard

POST CARD

Genuine Natural Color. Made by Dexter Press, Inc., West Nyack, N. Y.