

C37

P 1003

Westchester County Department of Health
Division of Environmental Sanitation

WELL COMPLETION REPORT

This report is to be completed by well driller and submitted to Health Department, together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality, before certificate of construction compliance is issued.

580 S

Well construction to be in accordance with Bulletin SD-62
"RULES & REGULATIONS RELATING TO INDIVIDUAL WATER SUPPLIES"

LOCATION: MUNICIPALITY CARMEL, NY MAP 107 SECTION 820 BLOCK 3 LOT 50

WELL OWNER: GERARDI LAKE MAC GREGOR MADONNA N.Y.
Name Street Address City and Town

WELL DRILLER: J. TORLISHA SONS MARK AVE ARMONK N.Y.
Name Street Address City and Town

CASING DETAILS		YIELD TEST		WATER LEVEL		SCREEN DETAILS	
Length:	<u>50</u> Feet	<input checked="" type="checkbox"/> Bailed <input checked="" type="checkbox"/> Pumped	<u>6</u> Hours	Static:	<u>32</u> Feet	Make:	
Diameter:	<u>6</u> Inches	Yield:	<u>10</u> G.P.M.	When Bailed or Pumped	<u>175</u> Feet	Length	Ft. Slot Size
Kind:	<u>Steel</u>					Diameter	In.

TOTAL DEPTH OF WELL 225 FEET

WELL LOG

Depth From Ground Surface	Give description of formations penetrated, such as: peat, silt, sand, gravel, clay, hardpan, shale, sandstone, granite, etc. Include size of gravel (diameter) and sand (fine, medium, coarse), color of material, structure (Loose, packed, cemented, soft, hard). For example: 0 ft. to 27 ft. fine, packed, yellow sand; 27 ft. to 134 ft. gray granite.
<u>0 Ft. to 39 Ft.</u>	<u>HARD PAN</u>
<u>39 Ft. to 180 Ft.</u>	<u>GRAY ROCK</u>
<u>180 Ft. to 225 Ft.</u>	<u>BROWN ROCK</u>
<u>Ft. to Ft.</u>	

RECEIVED

NOV 9 1981

PUTNAM COUNTY
DEPT. OF HEALTH

Date Well Was Completed 7/3/81

Date of Report 10/22/81

Well Driller James Torlish
Signature