C48

Westchester County Department of Health
Division of Environmental Sanitation

LAKE CARMEL
P1007

41 25 31
73 43 51

WELL COMPLETION REPORT

This report is to be completed by well driller and submitted to Health Department, together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality, before certificate of construction compliance is issued.

835, H

Well construction to be in accordance with Bulletin SD-62
"RULES & REGULATIONS RELATING TO INDIVIDUAL WATER SUPPLIES"

FILED MAP # 1589

LOCATION: MUNICIPALITY CARMEL SECTION _____ BLOCK _____ LOT 1

WELL OWNER: DALY & LOBUE (Name) BRIGHTVIEW CT (Street Address) CARMEL (City and Town)

WELL DRILLER: WRAGG BROS. WELL DRILLING CO. (Name) ROUTE 7, WILTON, CT. (Street Address) 06897 (City and Town)

CASING DETAILS	YIELD TEST	WATER LEVEL	SCREEN DETAILS
Length: 50 Feet	Bailed or XX Pumped 6 Hours	(measure from land surface) Static: 10 Feet	Make: NONE
Diameter: 6 Inches	Yield: 5 G.P.M.	When Bailed or Pumped 325 Feet	Length NONE Ft. Slot Size
Kind: STEEL			Diameter NONE In.

TOTAL DEPTH OF WELL 325 FEET

WELL LOG

Depth From Ground Surface	Give description of formations penetrated, such as: peat, silt, sand, gravel, clay, hardpan, shale, sandstone, granite, etc. Include size of gravel (diam) and sand (fine, medium, coarse), color of material, structure (loose, packed, cemented, soft, hard). For example: 0 ft. to 27 ft. fine, packed, yellow sa 27 ft. to 13¼ ft. grey granite.
0 Ft. to 40 Ft.	CLAY AND BOULERS.
40 Ft. to 50 Ft.	DARK GREY GRANITE.
50 Ft. to 325 Ft.	DARK GREY GRANITE, WITH SOME QUARTZ.
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	

Date Well Was Completed 9/22/78 Date of Report 10/25/78

Well Driller Bruce Wragg