/71

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

C61 MOHEGAN

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1014

OWNER	NAME: FILIPPO BRONCO		ADDRESS: Center Road, Mahopac, NY 10541			
LOCATION OF WELL	(No. & Street): Center Road		(Town): Mahopac, NY		(Lot Number):	
PROPOSED USE OF WELL	[X] DOMESTIC	[ ] BUSINESS ESTABLISHMENT	[ ] FARM	[ ] TEST WELL	730' S	
	[ ] PUBLIC SUPPLY	[ ] INDUSTRIAL	[ ] AIR CONDITIONING	[ ] OTHER (Specify)		
DRILLING EQUIPMENT	[ ] ROTARY	[X] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)		
CASING DETAILS	LENGTH (feet): 131	DIAMETER (inches): 6	WEIGHT PER FOOT: 17	[X] THREADED [ ] WELDED	DRIVE SHOE: [X] YES [ ] NO	WAS CASING GROUTED? [X] YES [ ] NO
YIELD TEST	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	HOURS: 4	G.P.M.: 8	YIELD (G.P.M.): 8
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet): 30		DURING YIELD TEST (feet): 260		Depth of Completed Well in feet below Land surface: 260	
SCREEN DETAILS	MAKE:				LENGTH OPEN TO AQUIFER (feet):	
	SLOT SIZE:	DIAMETER (inches):	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches):	FROM (feet): TO (feet):

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	120	Hardpan & boulders
120	260	Medium to hard granite

Sketch exact location of well with distances, to at least two permanent landmarks.



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE
260	8

Center Road

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
		Robert M. Mill

MILL DRILLING INC.
Mohegan