C67 LAKE CARMEL

Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1016

41 25 20 73 41 00

OWNER	NAME: American Builders, Inc.	ADDRESS: c/o Carl Holman, 9 Hazen Lane, Carmel, NY 1051
LOCATION OF WELL	(No. & Street): Dixon Lake	(Town): Carmel, NY (Lot Number):

PROPOSED USE OF WELL: [X] DOMESTIC [ ] BUSINESS ESTABLISHMENT [ ] FARM [ ] TEST WELL [ ] PUBLIC SUPPLY [ ] INDUSTRIAL [ ] AIR CONDITIONING [ ] OTHER (Specify) 740 C

DRILLING EQUIPMENT: [ ] ROTARY [X] COMPRESSED AIR PERCUSSION [ ] CABLE PERCUSSION [ ] OTHER (Specify)

CASING DETAILS	LENGTH (feet)	DIAMETER (inches)	WEIGHT PER FOOT			DRIVE SHOE	WAS CASING GROUTED
	22	6	17	[ ] THREADED	[ ] WELDED	[X] YES [ ] NO	[X] YES [ ] NO

YIELD TEST				HOURS	G.P.M.	YIELD (G.P.M.)
	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	4	5	5

WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)	DURING YIELD TEST (feet)	Depth of Completed Well in feet below land surface:
	20	365	365

SCREEN DETAILS	MAKE				LENGTH OPEN TO AQUIFER (feet)	
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches) FROM (feet)	TO (feet)

DEPTH FROM LAND SURFACE FEET	TO FEET	FORMATION DESCRIPTION
0	10	Sandy clay.
10	365	Hard granite.

Sketch exact location of well with distances, to at least two permanent landmarks.



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

COMMON ROAD

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
11/9/84	11/12/84	Robert M Mill, President

MILL DRILLING, INC.