LAKE CARMEL

Division of Environmental Health Services
COUNTY OFFICE BUILDING · CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

K15 | REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION | P 1039

41 29 53 73 44 42

OWNER	NAME: Quiet-Sun Enterprises, Inc.	ADDRESS: P.O. Box 424, Patterson, New York 12563
LOCATION OF WELL	(No. & Street): Dean Road	(Town): Kent, New York; (Lot Number): -

PROPOSED USE OF WELL: [X] DOMESTIC [ ] BUSINESS ESTABLISHMENT [ ] FARM [ ] TEST WELL [ ] PUBLIC SUPPLY [ ] INDUSTRIAL [ ] AIR CONDITIONING [ ] OTHER (Specify) 655 L

DRILLING EQUIPMENT: [ ] ROTARY [X] COMPRESSED AIR PERCUSSION [ ] CABLE PERCUSSION [ ] OTHER (Specify)

CASING DETAILS	LENGTH (feet)	DIAMETER (inches)	WEIGHT PER FOOT		DRIVE SHOE	WAS CASING GROUTED?
	20'-6"	6	19	[X] THREADED [ ] WELDED	[X] YES [ ] NO	[X] YES [ ] NO

YIELD TEST		HOURS	G.P.M.	YIELD (G.P.M.)
[ ] BAILED [ ] PUMPED [X] COMPRESSED AIR		4	20	20

WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)	DURING YIELD TEST (feet)	Depth of Completed Well in feet below land surface
	20	265	265

SCREEN DETAILS	MAKE				LENGTH OPEN TO AQUIFER (feet)	
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches)	FROM (feet) / TO (feet)

DEPTH FROM LAND SURFACE FEET	TO FEET	FORMATION DESCRIPTION
0	6	Soft Clay & Boulders
6	8	Soft Weathered Bedrock
8	265	Med-Hard Grey & Black Granite

Sketch exact location of well with distances, to at least two permanent landmarks



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE
200	4-1/4
265	20

RECEIVED MAY - 9 1983 PUTNAM COUNTY DEPT. OF HEALTH

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
12/27/82	1/3/83	Robert M Mill

MILL DRILLING, INC.