WELL COMPLETION REPORT
3/71

PUTNAM COUNTY DEPARTMENT OF HEALT
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YOR

K4 LAILE 41 27 58 CARMEL 33 40 28

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1059

OWNER	NAME: McGlasson Builders		ADDRESS: 93 Gleneida Avenue, Carmel, N.Y.	
LOCATION OF WELL	(No. & Street): Baldwin Road		(Town): Kent	(Lot Number): # 3
PROPOSED USE OF WELL	[X] DOMESTIC; [ ] PUBLIC SUPPLY	[ ] BUSINESS ESTABLISHMENT; [ ] INDUSTRIAL	[ ] FARM; [ ] AIR CONDITIONING	[ ] TEST WELL; [ ] OTHER (Specify) 645 S
DRILLING EQUIPMENT	[ ] ROTARY	[X] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)
CASING DETAILS	LENGTH (feet): 20'	DIAMETER (inches): 6"	WEIGHT PER FOOT: 19	[X] THREADED [ ] WELDED; DRIVE SHOE [X] YES [ ] NO; WAS CASING GROUTED? [X] YES [ ] NO
YIELD TEST	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	HOURS: 2; G.P.M.: 8; YIELD (G.P.M.): 8
WATER LEVEL	MEASURE FROM LAND SURFACE – STATIC (Specify feet): 35'	DURING YIELD TEST (feet): total drawdown	Depth of Completed Well in feet below land surface: 360'	
SCREEN DETAILS	MAKE:			LENGTH OPEN TO AQUIFER (feet):
	SLOT SIZE:	DIAMETER (inches):	IF GRAVEL PACKED: Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches): FROM (feet): TO (feet):

DEPTH FROM LAND SURFACE FEET to FEET		FORMATION DESCRIPTION
0	12	overburden
12	360	ledge

Sketch exact location of well with distances, to at least two permanent landmarks.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
6/13/80	6/22/80	[signature]