WELL COMPLETION REPORT
3/71

LAKE CARMEL
41 28 01 73 39 22

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING · CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1068

OWNER	NAME: Joseph Pulcz (No. & Street)	ADDRESS: Ridgeway & Montrose Dr. (Town)		(Lot Number)
LOCATION OF WELL	Ridgeway & Montrose Dr. Carmel, New York			
PROPOSED USE OF WELL	[X] DOMESTIC; [ ] BUSINESS ESTABLISHMENT; [ ] FARM; [ ] TEST WELL; [ ] PUBLIC SUPPLY; [ ] INDUSTRIAL; [ ] AIR CONDITIONING; [ ] OTHER (Specify) 640 S			
DRILLING EQUIPMENT	[X] ROTARY; [ ] COMPRESSED AIR PERCUSSION; [ ] CABLE PERCUSSION; [ ] OTHER (Specify)			
CASING DETAILS	LENGTH (feet): 20	DIAMETER (inches): 6	WEIGHT PER FOOT: 19	[X] THREADED [ ] WELDED; DRIVE SHOE [ ] YES [X] NO; WAS CASING GROUTED? [X] YES [ ] NO
YIELD TEST	[ ] BAILED; [ ] PUMPED; [X] COMPRESSED AIR	HOURS: 1½	G.P.M.: 10	YIELD (G.P.M.): 10
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet): 35 Ft	DURING YIELD TEST (feet): 205	Depth of Completed Well in feet below Land surface: 205	
SCREEN DETAILS	MAKE: None			LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE: 6"	DIAMETER (inches): 6"	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches): / GRAVEL SIZE (inches) / FROM (feet) / TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	205	Black & White Granite

Sketch exact location of well with distances, to at least two permanent landmarks.



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
June 22 1972	July 19 1972	[signature]