Division of Environmental Health Services
COUNTY OFFICE BUILDING · CARMEL, NEW YORK

LAKE CARMEL

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

K5

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P 1069

41 28 04 73 39 19

OWNER	NAME: Tony Ginese	ADDRESS: Lake Carmel N.Y.
LOCATION OF WELL	(No. & Street)	(Town) Lake Carmel N.Y. (Lot number)
PROPOSED USE OF WELL	[X] DOMESTIC [ ] BUSINESS ESTABLISHMENT [ ] FARM [ ] TEST WELL [ ] PUBLIC SUPPLY [ ] INDUSTRIAL [ ] AIR CONDITIONING [ ] OTHER (Specify)	655 5
DRILLING EQUIPMENT	[ ] ROTARY [X] COMPRESSED AIR PERCUSSION [ ] CABLE PERCUSSION [ ] OTHER (Specify)	

CASING DETAILS	LENGTH (feet)	DIAMETER (inches)	WEIGHT PER FOOT			DRIVE SHOE	WAS CASING GROUTED
	66	6	19	[X] THREADED	[ ] WELDED	[X] YES [ ] NO	[X] YES [ ] NO

YIELD TEST				HOURS	D.P.M.	YIELD (D.P.M.)
	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	2	5	5

WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)	DURING YIELD TEST (feet)	Depth of Completed Well in feet below land surface
	50	total drawdown	320

SCREEN DETAILS	MAKE					LENGTH OPEN TO AQUIFER (feet)	
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches)	FROM (feet)	TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION	Sketch exact location of well with dimension, to at least two permanent locations.
0	15	boulders bankrun	
15	43	clay	
49	56	sandstone	
56	320	granite	

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
9/1/75	10/3/75	[signature]

Boyd Artesian Well Co., Inc.
R. D. 5 - Route 52
Carmel, N.Y. 10512