WELL COMPLETION REPORT

K50 LAKE CARMEL

PUTNAM COUNTY DEPARTMENT OF HEALTH
Bureau of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

41 26 52 73 40 16 P1070

OWNER	NAME: McGlascon Builders		ADDRESS: Main St. Carmel, NY	
LOCATION OF WELL	(No. & Street): Wingdale Rd.		(Town): Kent	(Tax Number)
PROPOSED USE OF WELL	[X] DOMESTIC	[ ] BUSINESS ESTABLISHMENT	[ ] FARM	[ ] TEST WELL
	[ ] PUBLIC SUPPLY	[ ] INDUSTRIAL	[ ] AIR CONDITIONING	[ ] OTHER (Specify)

730 S.

DRILLING EQUIPMENT	[ ] ROTARY	[X] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)		
CASING DETAILS	LENGTH (feet): 20	DIAMETER (inches): 7	WEIGHT PER FOOT: 25	[X] THREADED [ ] WELDED	SEALED FROM SURFACE: [X] YES [ ] NO	WAS CASING GROUTED: [X] YES [ ] NO
YIELD TEST	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	DURATION: 2	G.P.M.: 6	YIELD (G.P.M.): 6
WATER LEVEL	MEASURE FROM LAND SURFACE - STATIC (before test): 75'		DURING YIELD TEST (feet): total drawdown		Depth of Completed Well in feet below land surface: 278	
SCREEN DETAILS	MAKE					LENGTH GROUT TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	SF GRAVEL PACKING	Diameter of well including gravel pack (inches)	GRAVEL SIZE (inches)	FROM (feet) / TO (feet)

DEPTH FROM LAND SURFACE (feet) to (feet)		FORMATION DESCRIPTION
0	2	overburden
2	278	ledge

If well was tested at different depths during drilling, fill below:

DEPTH	GALLONS PER MINUTE

DATE WELL COMPLETED: 8/29/75

DATE OF REPORT: 9/3/75

WELL DRILLER (Signature): Harry Van Boen

Boyd Artesian Well Co., Inc.
R. D. 5 - Route 52
Carmel, N.Y. 10512