WELL COMPLETION REPORT
3/71

LAKE CARMEL
41 27 15 73 39 25

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1076

OWNER	NAME: Cosmo Rietano	ADDRESS: Purchase Rd., Lake Carmel
LOCATION OF WELL	(No. & Street): Purchase Rd. (Town): Lake Carmel N.Y.	(Lot Number):
PROPOSED USE OF WELL	[X] DOMESTIC; [ ] BUSINESS ESTABLISHMENT; [ ] FARM; [ ] TEST WELL; [ ] PUBLIC SUPPLY; [ ] INDUSTRIAL; [ ] AIR CONDITIONING; [ ] OTHER (Specify)	610 S
DRILLING EQUIPMENT	[ ] ROTARY; [X] COMPRESSED AIR PERCUSSION; [ ] CABLE PERCUSSION; [ ] OTHER (Specify)	
CASING DETAILS	LENGTH (feet): 72' DIAMETER (inches): 7" WEIGHT PER FOOT: 26 [X] THREADED [ ] WELDED DRIVE SHOE: [X] YES [ ] NO WAS CASING GROUTED? [X] YES [ ] NO	
YIELD TEST	[ ] BAILED [ ] PUMPED [X] COMPRESSED AIR HOURS: 2 G.P.M.: 5 YIELD (G.P.M.): 5	
WATER LEVEL	MEASURE FROM LAND SURFACE – STATIC (Specify feet): 3' DURING YIELD TEST (feet): Total drawdown Depth of Completed Well in feet below Land surface: 140	
SCREEN DETAILS	MAKE: LENGTH OPEN TO AQUIFER (feet): SLOT SIZE: DIAMETER (inches): IF GRAVEL PACKED: Diameter of well including gravel pack (inches): GRAVEL SIZE (inches): FROM (feet): TO (feet):	

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	48	Hardpan - clay
48	70	Sandstone
70	120	Soft grey granite
120		Sand seam
121	140	Sand stone

Sketch exact location of well with distances, to at least two permanent landmarks.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

BOYD ARTESIAN WELL CO.
ROUTE 52, CARMEL, N.Y.

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
9/24/72	11/6/72	[illegible]