

318

BREWSTER

Westchester County Department of Health
Division of Environmental Sanitation
41 25 95 73 36 19

P1129

WELL COMPLETION REPORT

This report is to be completed by well driller and submitted to Health Department, together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality, before certificate of construction compliance is issued.

Well construction to be in accordance with Bulletin SD-62
"RULES & REGULATIONS RELATING TO INDIVIDUAL WATER SUPPLIES"

625 S

LOCATION: MUNICIPALITY Brewster SECTION _____ BLOCK _____ LOT 96-1-957

WELL OWNER: Mike Biglecki Locust Rd. Brewster
Name Street Address City and Town

WELL DRILLER: Torkish & Sons Maple Ave Armonk N.Y.
Name Street Address City and Town

CASING DETAILS		YIELD TEST		WATER LEVEL		SCREEN DETAILS	
Length:	175 Feet	Bailed		(measure from land surface)		Feet	Make:
		or Pumped 6 Hours		Static: 110			
Diameter:	6 Inches	Yield:	5 G.P.M.	When Bailed or Pumped	600 Feet	Length	Slot Size
Kind:	STEEL					Diameter	In.

TOTAL DEPTH OF WELL 645 FEET

WELL LOG

Depth From Ground Surface	Give description of formations penetrated, such as: peat, silt, sand, gravel, clay, hardpan, shale, sandstone, granite, etc. Include size of gravel (diameter) and sand (fine, medium, coarse), color of material, structure (Loose, packed, cemented, soft, hard). For example: 0 ft. to 27 ft. fine, packed, yellow sand; 27 ft. to 134 ft. gray granite.
0 Ft. to 165 Ft.	Hard pan & clay
165 Ft. to 310 Ft.	Gray Rock
310 Ft. to 440 Ft.	Green Rock
440 Ft. to 570 Ft.	Brown Rock
570 Ft. to 645 Ft.	Gray Rock
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	

Date Well Was Completed 8/31/83

Date of Report 12/10/83

Well Driller Quinn Torkish
Signature