WELL COMPLETION REPORT 3/71

BREWSTER

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1136

41 25 33 73 35 49

OWNER	NAME: McGlasson Builders (No. & Street)	ADDRESS: Gleneida Ave. (Town)	Carmel, NY 10512 (Lot Number)	
LOCATION OF WELL	Overlook Dr. Brewster	Southeast		
PROPOSED USE OF WELL	[XX] DOMESTIC; [ ] BUSINESS ESTABLISHMENT; [ ] FARM; [ ] TEST WELL; [ ] PUBLIC SUPPLY; [ ] INDUSTRIAL; [ ] AIR CONDITIONING; [ ] OTHER (Specify)	635 S		
DRILLING EQUIPMENT	[ ] ROTARY; [X] COMPRESSED AIR PERCUSSION; [ ] CABLE PERCUSSION; [ ] OTHER (Specify)			
CASING DETAILS	LENGTH (feet): 165	DIAMETER (inches): 6	WEIGHT PER FOOT: 19	[XX] THREADED [ ] WELDED; DRIVE SHOE [X] YES [ ] NO; WAS CASING GROUTED? [X] YES [ ] NO
YIELD TEST	[ ] BAILED; [ ] PUMPED; [XX] COMPRESSED AIR	HOURS: 2	G.P.M.: 15	YIELD (G.P.M.): 15
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet): 45	DURING YIELD TEST (feet): total drawdown	Depth of Completed Well in feet below Land surface: 380	LENGTH OPEN TO AQUIFER (feet)
SCREEN DETAILS	MAKE			
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED: Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches) / FROM (feet) / TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	140	clay overburden
140	150	brown sandstone
150	380	grey granite

Sketch exact location of well with distances, to at least two permanent landmarks.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
2/21/84	7/16/84	