528 LAKE CARMEL

WELL COMPLETION REPORT
3/71

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

41 24 06 73 37 47

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P 1138

OWNER	NAME: Leonard Cerlich		ADDRESS: Putnam Avenue, Brewster, New York		
LOCATION OF WELL	(No. & Street): Putnam Avenue		(Town): Brewster		(Lot Number):
PROPOSED USE OF WELL	[X] DOMESTIC	[ ] BUSINESS ESTABLISHMENT	[ ] FARM	[ ] TEST WELL	435 S
	[ ] PUBLIC SUPPLY	[ ] INDUSTRIAL	[ ] AIR CONDITIONING	[ ] OTHER (Specify)	
DRILLING EQUIPMENT	[ ] ROTARY	[X] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)	
CASING DETAILS	LENGTH (feet): 226	DIAMETER (inches): 6	WEIGHT PER FOOT: 17	[X] THREADED [ ] WELDED	DRIVE SHOE [X] YES [ ] NO; WAS CASING GROUTED? [ ] YES [X] NO
YIELD TEST	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	HOURS: 4	G.P.M.: 10; YIELD (G.P.M.): 10
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet): 40	DURING YIELD TEST (feet): 325		Depth of Completed Well in feet below Land surface: 325	
SCREEN DETAILS	MAKE				LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches); FROM (feet); TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	220	Hardpan.
220	325	Hard granite.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

Sketch exact location of well with distances, to at least two permanent landmarks.



DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
9-2-76	9-9-76	Robert M Mill, President

MILL DRILLING, INC.