WELL COMPLETION REPORT
3/71

C119

Mohegan

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P915

OWNER	NAME Limelight Construction		ADDRESS			10
LOCATION OF WELL	Deer Lane, Austin Road (No. & Street)		Mahopac, N.Y. (Town)		10541	(Lot Number)
PROPOSED USE OF WELL	☒ DOMESTIC	☐ BUSINESS ESTABLISHMENT	☐ FARM	☐ TEST WELL	625	S
	☐ PUBLIC SUPPLY	☐ INDUSTRIAL	☐ AIR CONDITIONING	☐ OTHER (Specify)		
DRILLING EQUIPMENT	☐ ROTARY	☒ COMPRESSED AIR PERCUSSION	☐ CABLE PERCUSSION	☐ OTHER (Specify)		
CASING DETAILS	LENGTH (feet) 112'	DIAMETER (inches) 6"	WEIGHT PER FOOT 17	☒ THREADED ☐ WELDED	DRIVE SHOE ☒ YES ☐ NO	WAS CASING GROUTED? ☒ YES ☐ NO
YIELD TEST	☐ BAILED	☐ PUMPED	☒ COMPRESSED AIR	HOURS 7+	G.P.M. 10	YIELD (G.P.M.) 10
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)		DURING YIELD TEST (feet)		Depth of Completed Well in feet below Land surface: 200	
SCREEN DETAILS	MAKE					LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches) FROM (feet)	TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
1'	102'	overburden
102'	200'	bedrock chist

Sketch exact location of well with distances, to at least two permanent landmarks.



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
5/31/77		N. Anderson