OSCAWANA

WELL COMPLETION REPORT
3/71

C175

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Ser...
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P946

OWNER	NAME: Salvatore Martorano	ADDRESS: Lakewood Rd., Lake McGregor, Mahopac, N.Y.		
LOCATION OF WELL	(No. & Street): Lakewood Road, Lake McGregor, Mahopac, New York	(Town)		(Lot Number): 12
PROPOSED USE OF WELL	[XX] DOMESTIC	[ ] BUSINESS ESTABLISHMENT	[ ] FARM	[ ] TEST WELL 790 S
	[ ] PUBLIC SUPPLY	[ ] INDUSTRIAL	[ ] AIR CONDITIONING	[ ] OTHER (Specify)
DRILLING EQUIPMENT	[ ] ROTARY	[XX] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)
CASING DETAILS	LENGTH (feet): 60	DIAMETER (inches): 6	WEIGHT PER FOOT: 17	[XX] THREADED [ ] WELDED
	DRIVE SHOE: [XX] YES [ ] NO	WAS CASING GROUTED? [ ] YES [XX] NO		
YIELD TEST	[ ] BAILED	[ ] PUMPED	[XX] COMPRESSED AIR	HOURS: 2
	G.P.M.: 5	YIELD (G.P.M.): 5		
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet): 60	DURING YIELD TEST (feet): 340	Depth of Completed Well in feet below Land surface: 340	
SCREEN DETAILS	MAKE			LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):
	GRAVEL SIZE (inches)	FROM (feet)	TO (feet)	

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	55	Hardpan.
55	340	Hard graygranite.

Sketch exact location of well with distances, to at least two permanent landmarks.



If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
7/21/72	7/28/72	Robert M Mill

MILL DRILLING, INC.