WELL COMPLETION REPORT
3/71

C20D

CROTON FALLS

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P 964

41 21 52 73 41 04

OWNER	NAME: Melnick Homes		ADDRESS:	
LOCATION OF WELL	(No. & Street): Munich Road		(Town): Croton Falls N.Y.	(Lot Number):
PROPOSED USE OF WELL	☒ DOMESTIC ☐ PUBLIC SUPPLY	☐ BUSINESS ESTABLISHMENT ☐ INDUSTRIAL	☐ FARM ☐ AIR CONDITIONING	☐ TEST WELL ☐ OTHER (Specify) 390 S
DRILLING EQUIPMENT	☒ ROTARY	☒ COMPRESSED AIR PERCUSSION	☐ CABLE PERCUSSION	☐ OTHER (Specify)

CASING DETAILS	LENGTH (feet)	DIAMETER (inches)	WEIGHT PER FOOT		DRIVE SHOE	WAS CASING GROUTED?
	50'	6"	19.45	☒ THREADED ☐ WELDED	☒ YES ☐ NO	☒ YES ☐ NO

YIELD TEST				HOURS	G.P.M.	YIELD (G.P.M.)
	☐ BAILED	☐ PUMPED	☒ COMPRESSED AIR	8	6	

WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)	DURING YIELD TEST (feet)	Depth of Completed Well in feet below Land surface:
	27'	170'	

SCREEN DETAILS	MAKE				LENGTH OPEN TO AQUIFER (feet)	
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):	GRAVEL SIZE (inches)	FROM (feet) / TO (feet)

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	56	Hard pan, sand, gravel
56	311	Hard granite rock.

Sketch exact location of well with distances, to at least two permanent landmarks.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
11-27-72	2-7-73	Frank Carroll Jr.