C22

WELL COMPLETION REPORT
3/71

41 23 30 73 42 48
LAKE CARMEL

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P 976

OWNER	NAME Sherwood Homes		ADDRESS Rt. 22 Pawling, NY	
LOCATION OF WELL	(No. & Street) Savage Prop.	Lake Casse Baldwin Lane	(Town) Carmel	(Lot Number)
PROPOSED USE OF WELL	[XX] DOMESTIC	[ ] BUSINESS ESTABLISHMENT	[ ] FARM	[ ] TEST WELL
	[ ] PUBLIC SUPPLY	[ ] INDUSTRIAL	[ ] AIR CONDITIONING	[ ] OTHER (Specify)
DRILLING EQUIPMENT	[ ] ROTARY	[X] COMPRESSED AIR PERCUSSION	[ ] CABLE PERCUSSION	[ ] OTHER (Specify)
CASING DETAILS	LENGTH (feet) 42	DIAMETER (inches) 6	WEIGHT PER FOOT 19	[X] THREADED [ ] WELDED
	DRIVE SHOE [XX] YES [ ] NO	WAS CASING GROUTED? [XX] YES [ ] NO		
YIELD TEST	[ ] BAILED	[ ] PUMPED	[X] COMPRESSED AIR	HOURS 2
	G.P.M. 10	YIELD (G.P.M.) 10		
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet) 30'	DURING YIELD TEST (feet) total drawdown	Depth of Completed Well in feet below Land surface: 205	
SCREEN DETAILS	MAKE			LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED:	Diameter of well including gravel pack (inches):
	GRAVEL SIZE (inches)	FROM (feet)	TO (feet)	

DEPTH FROM LAND SURFACE FEET	to FEET	FORMATION DESCRIPTION
0	25	clay overburden
25	205	grey granite

Sketch exact location of well with distances, to at least two permanent landmarks.

If yield was tested at different depths during drilling, list below

FEET	GALLONS PER MINUTE

DATE WELL COMPLETED	DATE OF REPORT	WELL DRILLER (Signature)
6/20/84	7/12/84	